

Attachment:

Emergency Action Plan (EAP) Preliminary Review Comments


RE:

Keuka Lake Outlet Dam
DEC Dam ID#: 053-0613

The Department of Environmental Conservation (“Department”) acknowledges receipt of the Emergency Action Plan for the above-noted dam. The Dam Safety Section has performed a preliminary cursory review of your EAP. The Department may follow up with additional comments on the EAP in the future.

The EAP should be distributed to all participants in the Notification Flow chart. You should not wait for Dam Safety’s final review comments before distributing the EAP.

MISSING OR INCORRECT	COMPONENT	COMMENTS
<input checked="" type="checkbox"/>	Dam Name and State Dam ID on cover	If Missing, Provide cover sheet with Dam Name and State Dam ID #
<input type="checkbox"/>	Notification Flowchart	Notification Flowchart must be included in the EAP. Revise the EAP and submit to the Department at the above address
<input checked="" type="checkbox"/>	DEC contact information	Please revise the Notification Flowchart by deleting the current references and replacing them with the following information: Primary Alon Dominitz, Chief (518) 402-8185 (office) (518) 852-0415 (cell) Backup NYSDEC Bureau of Flood Protection & Dam Safety (518) 402-8151
<input type="checkbox"/>	Inundation mapping	If not included, please submit to Department at above address
<input checked="" type="checkbox"/>	Indication of consultation, concurrence, and distribution to emergency managers. (Promulgation & Concurrence Form)	To be considered Final, the EAP must be coordinated with and accepted by local emergency responders. The EAP should be distributed to all appropriate parties. Submit the Promulgation and Concurrence Form to the Department at the above address.



Visual Observations

<i>DAM NAME</i>	Keuka Lake Outlet Dam				
<i>STATE ID</i>	053-0613	<i>SECTION</i>	B	<i>HAZARD CODE</i>	C
<i>COUNTY</i>	Yates			<i>INSPECTION DATE</i>	6/22/2011
<i>NEAREST DS CITY/TOWN</i>	Penn Yan			<i>INSPECTOR(S)</i>	JAS/KIM
<i>OWNER'S NAME</i>	KEUKA LAKE OUTLET COMPACT				
<i>DOWNSTREAM HAZARD</i>	High			<i>TOWNSHIP</i>	Town of Milo
<i>WATER LEVEL BEHIND DAM</i>	See photo				
<i>DRAIN OPERATION</i>	Reported to be functional by personnel on site				
<i>DEFICIENCIES</i>	Seepage				

The condition of the dam is similar to that observed during the 2009 visit to the site. The dam was jointly observed with operational staff associated with the dam:

1. Maintenance is planned for the old gate in the far left bay (photo #4)
2. There is seepage at various locations through the masonry joints (photo #3). The condition should be monitored.
3. Minor weedy growth in places.
4. A functional test of the gates by the Army Corps of Engineers was reported to be scheduled for this year. All gate were said to be fully operational.